



Special Advisory

Cargo Tank Vapor Recovery

Certification Testing

Number 317

July 2003

Evaluation Period of Internal Vapor Valves Extended until 12-31-2003

As you may be aware, the Air Resources Board (ARB) Enforcement Division enforces all requirements of the Cargo Tank Vapor Recovery Certification and Test Procedures. One of the requirements contained in the Certification and Test Procedures is that after the annual certification test, the cargo tank shall be maintained in compliance with the year round leak rate requirements.

We need to control the gasoline vapor emissions emitted to the atmosphere from cargo tanks because it contributes to photochemical smog and adverse health effects.

Industry has advised the ARB that some of the vapor recovery components, such as internal vapor valves, used on cargo tanks are defective and are causing the cargo tank to leak more than the allowable limit. Enforcement Division staff will be conducting inspections throughout the state to determine the magnitude of the situation.

Therefore, if your cargo tank is issued a Notice of Violation, and the violation is solely due to the defective internal vapor valve. I am willing to waive penalty for the violation if a detailed description of failure and the defective internal vapor valve is returned to the ARB for our evaluation. The waiving of the penalty is at the discretion of the ARB and expires 12-31-2003.

If you wish to participate in this program you must notify the ARB of the location, date, and time when the cargo tank will be repaired. An ARB representative will then witness the defective vapor valve being reworked and then take possession for our evaluation.

Please complete the reverse of the Advisory and submit it to the Air Resources Board with the defective internal vapor valve. If you wish to participate or you have any questions regarding this advisory, please contact my staff at 916-322-3951.

**James R. Ryden, Chief Enforcement Division
California Air Resources Board
P.O. Box 2815
Sacramento, CA 95812**

Return To:
California Environmental Protection Agency
Air Resources Board
Enforcement Division
P.O. Box 2815
Sacramento, CA 95812
(916) 327-1524 (916) 322-6950
cargotank@arb.ca.gov

ARB USE ONLY

NOV #: _____
CT#: _____

NOTIFICATION OF DEFECTIVE INTERNAL VAPOR VALVE

Please TYPE or PRINT

CARGO TANK OWNER/OPERATOR INFORMATION

Owner /Operator Name: _____ Phone: (____) _____

Company Name: _____

Mailing Address: _____

City

State

Zip Code

Notice of Violation ____ / ____ / ____ Date Removed From Service ____ / ____ / ____
Mo Day Year Mo Day Year

I hereby certify under penalty of perjury that all the information submitted herein is true and correct.

Printed Name

Signature

Title

Date

Detailed explanation of defective internal vapor valve failure: _____

TESTING INFORMATION

Test Company Name: _____ Phone: (____) _____

Mailing Address: _____

City

State

Zip Code

ANNUAL TEST Pressure Change _____ Vacuum Change _____ Internal Vapor Valve _____

I hereby certify under penalty of perjury that all Testing Information submitted herein is true and correct and that the tank described above has been tested in accordance with the procedures set forth by the California Air Resources Board and to the accuracy of the tests.

Date of Test ____ / ____ / ____ Test Conducted By _____

Printed Name

Signature